



Sprso Giro Troubleshooting

Error	the message Safety heating element (Error 02203) is shown in the display
Action	Let the machine cool down for a few minutes. The heating element safety will reset itself automatically, and the machine will be operational again.
Remark	<p>This display message may appear if the water temperature is set to the max value, and multiple drink with a large volume have been dispensed. (for example, americano, lungo or hot water)</p> <p>The espresso machine heats up water after a drink selection is selected, and the start has been pressed. This reduces energy consumption when compared with machine with an internal hot water boiler, but when multiple drinks are dispensed in a very short period the heating element is activated almost continuously. A safety device may in that instance be activated to prevent that the heating element becomes too hot.</p>



Please wait for a few minutes.

The heating element safety device is automatically reset when the element has cooled down.



Do you have any questions or does the problem persist?
Please contact the helpdesk of your local service organization.